

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTIONPage 1 of 1

PATENT NO. : 7,426,900

APPLICATION NO.: 10/716,729

ISSUE DATE : Sep. 23, 2008

INVENTOR(S) : Brcka

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Abstract, at line 4, "prepare substrates for, and to process substrates by applying," should read -- prepare substrates for, and to process substrates by, applying--.

In Column 1, line 16, "sources, which utilizing" should read --sources, which utilize--.

In Column 2, line 41, "the ICP sources with a spiral coil produces" should read -- ICP sources with spiral coils produce--.

In Column 3, line 56, "source is provided." should read -- source are provided.--.

In Column 4, line 59, "FIG 6D, is a slot" should read -- FIG 6D is a slot--.

In Column 7, line 59, "which are practical and may be" should read -- which are practical may be--.

In Column 7, line 61, "I-ESIC device." should read --i-ESIC device.--.

In Column 8, line 7, "C<sub>cep</sub>" should read -- C<sub>cep</sub>--.

In Column 9, line 11, "FIG. 6A-6B show" should read -- FIGS. 6A-6B show--.

In Column 9, lines 24-25, delete "Express Mail No. EV354971157US,".

## MAILING ADDRESS OF SENDER (Please do not use customer number below):

Wood, Herron & Evans, L.L.P.  
441 Vine St., Suite 2700  
Cincinnati, OH 45202

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

U.S. Patent No.: 7,426,900  
Issue Date: September 23, 2008  
Serial No.: 10/716,729  
Applicant: Brcka  
Title: INTEGRATED ELECTROSTATIC INDUCTIVE COUPLING FOR  
PLASMA PROCESSING  
Attorney Docket: TAZ-240  
Confirmation No.: 6314

Cincinnati, Ohio 45202  
Electronically Filed  
August 28, 2009  
Certificate of Corrections Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Sir:

**REQUEST FOR CERTIFICATE OF CORRECTION**  
**(37 CFR §§ 1.322(a), 1.323)**

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent. The patent contains errors that occurred through the fault of the U.S. Patent and Trademark Office. The patent also contains errors in the specification and Abstract that occurred by Applicant.

Form PTO/SB/44 outlining the corrections to be made is submitted herewith.

Applicant submits herewith the fee of \$100 due as a result of this request. If any deficiencies or credits are necessary to complete this communication, please apply them to Deposit Account No. 23-3000.

Respectfully submitted,  
WOOD, HERRON & EVANS, L.L.P.  
By: / Joseph R. Jordan /  
Joseph R. Jordan, Reg. No. 25,686

2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202  
(513) 241-2324 (telephone)  
(513) 241-6234 (facsimile)